



REAR LAMPS Cont'd

LICENSE LAMP Cont'd



022-00788


HIGH MOUNT STOP LAMP SEDAN



022-00662

1 Lamp	4A5 945 122	4	73.90
<i>Mounted on Back Glass</i>			
2 Housing	4A5 945 121 01C		18.85
Socket, Bulb	8B3 945 265 A		1.80
Bulb (10)	92-95 N 903 605 01		.85
	96-97 N 900 510 02		1.50

HIGH MOUNT STOP LAMP WAGON



022-00663


1 Lens, Lamp	4A9 945 122	3	56.85
<i>Mounted on Liftgate Spoiler</i>			
2 Housing	4A9 945 121		44.85
Bulb	N 903 605 01		.85
	N 900 510 02		1.50

REAR BUMPER

Use Procedure Explanations 27 and 28 with the following text.

Refinish Rear Cover.....	1.4
Refinish Mouldings Complete.....	1.0
Refinish Center Moulding.....	.4
Refinish Outer Moulding.....	R/L .4
R&I Bumper Assy.....	.6
O/H Bumper Assy (Includes R&I).....	1.5

NOTE: All Parts in this section are included in overhaul unless noted otherwise.



022-00664

1 Bumper Assy (P)	92-94 4A0 807 301 B GRU	1.5	605.00
<i>100 Series, S4</i>			

A6	1995-97	4A0 807 301 AC GRU	1.5	605.00
	1998	4A0 807 301 AC GRU	1.5	605.00
	Wagon	4A0 807 301 AC GRU	1.5	605.00
S6		4A0 807 301 AC GRU	1.5	605.00
2 Cover, Rear (P)	100 Series, S4	92-94 4A0 807 305 GRU	1.5	567.00
A6	1995-97	4A0 807 305 BB GRU	1.5	544.00
	1998	4A0 807 305 BB GRU	1.5	544.00
	Wagon	4A0 807 305 BB GRU	1.5	544.00
S6		4A0 807 305 BB GRU	1.5	544.00
<i>(P) Paint to Match</i>				
3 Bar, Rein	Service w/Bumper Assy			
4 Support, Bumper	R/L 4A0 807 386-5		IOH	49.65
5 Deflector, Heat	4A0 807 515			26.85
<i>Included w/Bumper Assy</i>				
6 Moulding, Cover Center (P)				
	Sedan	4A5 807 443 GRU	#.3	164.60
	Wagon	4A9 807 443 A GRU	#.3	380.85
7 Moulding, Cover Outer (P)				
	R	4A0 807 460 GRU	#.3	77.55
	L	4A0 807 459 GRU	#.3	72.60
<i>(P) Paint to Match</i>				
<i>#w/Bumper Assy Removed, R&R Complete .5, Not Included in O/H</i>				
8 Bracket, Cover	R/L 4A0 807 253 C		IOH	4.25
9 Absorber, Impact	R/L 4A0 807 378-7		#.3	174.75
<i>#w/Bumper Assy Removed, Not Included in O/H</i>				

