

AUDI 100/200 1989-91

SECTION INDEX

A/C Refrigerant Capacities	90
ABS/Brakes	91
Air Bag System	91
Air Cleaner	94
Air Conditioning/Heater	90
Back Window	99
Center Console	95
Clear Coat Identification	88
Cooling	89
Cowl & Dash	95
Electrical	95
Emission System	95
Engine	94
Engine Mounts	94
Engine Oil Cooler	94
Exhaust	94
Front Bumper	89
Front Door	97
Front Drive Axle	93
Front Fender	90
Front Inner Structure	90
Front Lamps	89
Front Seat	96
Front Steering Linkage/Gear	93
Front Suspension	92
Fuel Tank	102
Grille	89
Hood	89
Information Labels	89
Instrument Panel	95
Intercooler	94
Liftgate	100
Luggage Lid	100
Paint Code Location	88
Quarter Glass	100
Quarter Panel	99
Rear Body	102
Rear Bumper	103
Rear Door	97
Rear Drive Axle	102
Rear Lamps	103
Rear Seat	96
Rear Suspension	101
Rocker/Pillars/Floor	96
Roof	98
Seat Belts	96
Special Cautions	88
Steering Pump	93
Steering Wheel/Column	93
Sunroof	99
Underhood Dimensions	90
Wheel	91
Windshield	95

SPECIAL CAUTIONS

AIR BAG

Refer to Procedure Explanation 29 for Supplemental Restraint/Air Bag Special Cautions.

ANTILOCK BRAKE SYSTEM

ABS

Manufacturer advises that ABS Control Unit be disconnected before welding and removed if a temperature of 85 degrees C (185 degrees F) is to be exceeded for more than 2 hours.

REFINISH BAKING

Manufacturer advises that after baking, sufficient cooling time should be allowed before attempting to start vehicle.

SUSPENSION

Manufacturer advises that new fasteners must be used whenever old fasteners are loosened or removed.

PAINT CODE LOCATION

Paint code located on luggage lid.

CLEAR COAT IDENTIFICATION

All metallic colors except Code L0A9 Pearl White are clear coat. L0A9 Pearl White is three stage finish.

Damaged Vehicles.
-888-256-7969 or 858/549-0629.